

DocuColor 1632/2240

PCL printer driver Release-note

8 Aug 2007
OPBG Client Driver Development

☐ Products

Xerox DocuColor 1632/2240

☐ Environment and File name and File size

English

Windows 2000/XP/Server 2003/Vista XCDC-Eng-Win2k-15Feb2007.zip 2,025,745 byte

☐ Version and Release date

English

Windows 2000/XP/Server 2003/Vista V1.2.4 2007/2/15

☐ Appendix to readme file

Appended

☐ Virus Check

Confirmed

☐ Changed Items

Actions taken in response to the troubles reported from the field and tests and the major changing in the tests.

The Following items, Fixed Problems and Specification Changes, are changes from DocuColor 1632/2240 PCL Driver Version 1.2.3.

Specification Changes:

SC No.	OS	Title
SC12558	Vista	Supporting Windows Vista : These SC require supporting Windows Vista at PCL driver.

Fixed Problems:

AR No.	OS	Title
AR86340	All	<FC-WC24><ProwebXS-460>Quality Loss with Secure Print.
AR81503	All	<FC>Image deletion in DCC400 PCL6 2up mode.(C244975)
AR58980	2k/XP	<FC>WinXP+Publisher2003+PCL 4up shows 16-720(C161585)
AR57180	2k/XP	<FC>016-720 happen with WinXP-E+Publisher 2003+PCL

Other 6 ARs are fixed on PCL driver platform, these problems are slight.

☐ Limitations

None.

☐ Known Problems

None

☐ WHQL Certified

Not Certified.

☐ Appendix

The details of the problem and specification changes are described following below.

SC No.	OS	Title	Reproduction Method or Details
SC12558	Vista	Supporting Windows Vista	These SC require supporting Windows Vista at PCL driver.

AR No.	OS	Title	Reproduction Method or Details
AR86340	All	<FC-WC24><ProwebXS-460>Quality Loss with Secure Print.	Customer is printing same job as Normal and as Secure. The file prints in both cases but the Secure Print output is low quality. No problem when using PS but Customer doesn't have the PS KIT"
AR81503	All	<FC>Image deletion in DCC400 PCL6 2up mode.(C244975)	When customer sets below settings, image deletion happens. <Driver> Print Page Mode:on Resolution :300dpi <PowerPoint> Frame slides: ON
AR58980	2k/XP	<FC>WinXP+Publisher2003+PCL 4up shows 16-720(C161585)	When the attached file (a business card creation document) was printed from the XP, the device's UI displayed the 016-720 error.
AR57180	2k/XP	<FC>016-720 happen with WinXP-E+Publisher 2003+PCL	When you send the customer's print file 16-720 happen. - Publisher2003+Win2k/XP -> NG - Publisher2003SP1 -> OK.

-- End of Document. --